

57

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID : E1/4 Sec. 16, T17N-R1E

41701162000

DATE	CREW	MONUMENT TYPE -----
November 11, 2016	Zachariah P. Dechant Gary L. Dechant	Replaced broken Harrison with new Harrison and 6' anchor in concrete. Set new sign 1.5' west. Wood post 2' east.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Reset destroyed 3/4"x24"round iron bar down 10"	N70E	20.70"
2) Found 3/4" round iron bar, west side of fence, down 6"	South	20.04' (20;00')
3) Set 3/4"x24" round iron bar, down 12" in field	S69W	26.24'
4) Reset leaning 3/4" round iron bar, lowered 12" in field	North	20.20'



I, Bryan H. Meyer, do hereby certify that on the 5th day of January 19 84, I found (evidence) ~~(no evidence)~~ of the East 1/4 corner of Section 16, T 17 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of corner establishment since Original Government Survey

A crew from H. A. Sime and Associates was here in April of 1975, and found an unrecorded 1" iron pipe.

Description of corner evidence found:

I found a 1" iron pipe at a 2-way fence corner and accepted it as the corner.

Dated this 5th day of Jan. 19 84.

Bryan H. Meyer
Deputy County Surveyor
Title

See Reverse Side For Maintenance



COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Crew: Meyer, Perrigo
Date: January 5, 1984 - 10:30 A.M.
Weather: Windy, P. Cloudy, 30°±
Witnesses to corner location:

Bryan H. Meyer

Dennis Perrigo

APPROVED: Harley A. Sime
Monroe County Surveyor



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

- = Set 3/4" x 24" iron bar
- = Set 1" x 17" iron pipe.



~~City, Village or~~ Town of Oakdale
County of Monroe