

# U.S. LAND CORNER MAINTENANCE

Corner ID : SE Sec.20, T17N-R1E


41701200000

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
May 10, 2013	Zachariah P.Dechant Gary L. Dechant	Harrison destroyed during road construction reset from remaining ties and old survey points Reset, drove two 1"x24" iron pipes, one on top of other.

References:

	<u>Bearing</u>	<u>Distance</u>
4" White Pine now(12")		40.68'
7" Black Cherry (stump)		25.68'
Set 1"x24" iron pipe down 18" toe of slope of bank of road	N30E	35.13'
Set 1"x24" iron pipe on slope of hill	S30W	67.34'

NOTE: Iron pipe references set on straight line with SE corner Section 20.



CERTIFICATE

CERTIFIED LAND CORNER

No. 89

417 01200000

I, Harley A. Sime, do hereby certify that on the 26th day of December 1979, I found ~~(evidence)~~ (no evidence) of the Northwest corner of Section 28, T 17 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

No known history since the original government survey.

Description of corner evidence found:

Projected a line through the NE corner and the N¼ corner of Section 28 and intersected it with a projected line through the NW corner and W¼ corner of Section 21. This corner fits existing occupied conditions well.

Dated this 10th day of Feb 1981

Approved: **HARLEY A. SIME**  
**MONROE CO. SURVEYOR**



Title

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Dechant  
Tormoen  
Meyer



T 17 N R 1 E

WISCONSIN

(All trees double blazed with N&C's set)

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

PLACED  
COUNTY SURVEYOR'S  
SIGN 6-16-87

or Town Oakdale

County of Monroe