

133/121

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


**Corner ID : SE Sec.36, T18N-R1W
21801360000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE -----</u>
September 3, 2015	Zachariah P. Dechant Gary L. Dechant	Existing Harrison, top broke off, down 3" In center line Road. Fence running north along east side cranberry bed. 10 east of ditch to south

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, 4' south of fence corner at SE corner cranberry bed	North	43.37'
2) Set 3/4"x24" round iron bar, down 6", 14' north of road center line	N79E	67.76'
3) Set 3/4"x24" round iron bar, down 6", 12' south of road center line	S79W	46.34'
4) Set 3/4"x24" round iron bar, down 6' on south bank of road	South	13.49'

Harrison and reference markers set on straight lines.



I, Gary L. Dechant, do hereby certify that on the 23rd day of December 19 86, I found (evidence) ~~(no evidence)~~ of the SW corner of Section 31, T 18 N, R 1E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 7th day of Jan. 19 87.

Gary L. Dechant
Registered Land Surveyor, 1744
Title

History of corner establishment since Original Government Survey

Fred Holden set an iron rod here in 1904.

**See Reverse Side
For Maintenance**

Description of corner evidence found:




Could not find Holden's monument. Corner re-established in centerline of road and on line with north-south fences.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

David E. Madison

Gary L. Dechant



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or Town~~ Byron
County of Monroe

COUNTY SURVEYOR FORM NO. 1