

31

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

Corner ID : SW Sec.5, T17N-R1E

41701060000

DATE	CREW	MONUMENT TYPE -----
July 11, 2018	Zachariah P.Dechant Gary L. Dechant	Replaced broken Harrison with 1 1/4"x6' round iron bar in concrete. Set sign 2' north. Wood post 2' NE. 110' NE of center line Hwy. "12" & "16"

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x4' round iron bar, up 2" 1' south of r/w fence with old survey sign	S6°45'E	67.55'
2) Set 3/4"x4', round iron bar, up 2", 1' south of r/w fence with old survey sign	S18°00'W	60.24'
3) Set 3/4"x4'round iron bar, up 2", 3' south of r/w fence, 3' SE of power pole with old survey sign	S47°54'W	68.77'

Gary L. Dechant

July 21, 2018

I, Lawrence A. Feddersen, do hereby certify that on the 1 day of December 19 77, I found ~~(XXXXX)~~ (no evidence) of the Southwest corner of Sec. 5, T 17 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 1 day of DEC. 19 77.

Lawrence A. Feddersen
Registered Land Surveyor
Title

History of original corner establishment:

In 1904 Fred Holden set an iron pipe at this corner, but it was not found.

Description of corner evidence found:


A Harrison monument was set by extending East, on a straight line and doubling the distance between monuments found at the S $\frac{1}{4}$ corner of Sec. 6 and the SW corner of the SE $\frac{1}{4}$ -SE $\frac{1}{4}$, Sec. 6.

**See Reverse Side
For Maintenance**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

- Lawrence Feddersen
- Mark Heidecke
- Douglas Malliet



COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~XXXXXX~~ Town of Oakdale
County of Monroe