CSR 1375

SURVEY OF PART OF SECTION 16 RANGE 4 WEST



Chainmen:
Ben Fox
Grant Henderson

Flagmen
Ben Fox
Earl Fox

Started at E 1/4 Cor. which I established on statement of Earl Fox, who was along on a previous survey. He certified Cor. was in center of highway and in line with old fence, remains of which I found. Found old stump, which checked with original bearings to the fence line but this would throw the Cor. 191 Ft. E.

Ran W on 0 Var. Set temporary 1/16 Cor. Posts and intersected W side section fence at 54*92.5 fell in fence corner that S55E 30.5 links this tree was marked by Holden. I corrected my random line and set permanent Cor. posts. 299ft. N of W. 1/4 Cor. which ~~[illegible]~~ checked perfectly with bearings , ~~[illegible]~~

Corrected Var. 3°30'

Bearings ---

E 1/4	[illegible]	[illegible]	[illegible]	[illegible]
	D 0	[illegible]	S 75 E	20 ft.
W 1/4	J 0	14	S 55 E	30.5 links
1	W 0	17	N 79 E	23.5 ft
	N 0	16	S 42 W	24.5 "
2	N 0	11	N 27 E	16.5 "
	B 0	14	S7W	11 ft 9 in.

Certify this to be Correct.
A. A. Bergman
Surveyor.

May 19-20 1930

CSR 1375