CERTIFICATE

I, Harley A. Sime, do hereby certify that on the twelfth day of June 1980, I found (~~evidence~~) (no evidence) of the North¼ corner of Section 2, T 18 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 25th day of Feb. 1981.

Harley A. Sime - R.L.S. 355

County Surveyor-Monroe County, Wisconsin.
Title

CERTIFIED LAND CORNER

No. 4

41901350020

History of corner establishment since Original Government Survey

None recorded since the original government survey.

Description of corner evidence found:

Set an iron pipe on line and equidistant between the section corners.

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Malcom Scott Sowers

Todd Tormoen

Approved: HARLEY A. SIME
MONROE CO. SURVEYOR



Set 2" iron pipe, up 12" above present water level.



T 18 N R 1 E

WISCONSIN

PLACED
COUNTY SURVEYOR'S
SIGN 6-12-87

SURVEY CONTROL ORDER

Horizontal	
Vertical	

WISCONSIN COORDINATE SYSTEM

	East (X)	North (Y)	Elevation (Z)	Zone
Corner				
Control Sta. Name				

~~City, Village or~~ Town of Byron

County of Monroe

Wisconsin