S89°08'58"E

2644.68'

West 1/4 corner, Section 34, T19N, R4W.

Center 1/4 corner, Section 34, T19N, R4W.

S89°08'58"E

1316.85'

CE1/16 corner, Section 34, T19N, R4W.

SURVEYOR'S CERTIFICATE: I, Bryan H. Meyer, being a duly qualified surveyor, do hereby certify that by the order and under the direction of Mr. LaVern Konze, I have located the North and East lines of the NW¼-SE¼, Section 34, T19N, R4W, Town of Little Falls, Monroe County, Wisconsin and that the within map is a true and correct representation of the lines surveyed, to the best of my knowledge and belief.

Bryan H. Meyer, Registered Land Surveyor

H. A. Sime and Associates

P. O. Box 705, Tomah, Wisconsin

Phone:(608)-372-5392

The bearings shown hereon are referenced to the East - West ¼ line of Section 34; said line is ASSUMED to bear S89°08'58"E.

N

W E

S

WISCONSIN BRYAN H. MEYER S-1712 TOMAH, WIS. LAND SURVEYOR

⊕ = Cast iron Harrison marker found

● = 1 1/4" round iron bar found

○ = 1 1/4" x 30" round iron bar set weighing 4.17 lbs./lin. ft.

1320.17'

S0°39'42"W

SCALE: 1" = 200'

Dated this 15th day of July, 1991, at Tomah, Wisconsin.

CSR 1978

PLAT OF SURVEY

of the North and East lines of the NW¼-SE¼, Section 34, T19N, R4W, Town of Little Falls, Monroe County, Wisconsin.

4/24

C1/16SE corner, Section 34, T19N, R4W.

COPY