Sec 24 T15 2W

Surveyed and subdivided Sec 24 in Town 15 Range 2W and proceeded as follows: Commenced at the N E corner of the Section, the same being a known corner, at 40 chains running South identified 1/4 corner from old Bearing, a Thorn 5 N 29 W 22 the other bearing could not be found at 80 chs set Temporary stake no bearings could be found - Returned to the place of beginning run West. at 40 chains set temporary stake. Bearings gone. at 80 chains and 12 feet, found in new 16 feet south of corner of Sect 13, 14 23 & 24. Corrected East. and made 1/4 post permanent. Returned to corner of 13 14 23 & 24 run South at 40 chs set Temporary 1/4 post and at 80 chains struck corner of 23 24 25 & 26. it being a known corner. Thence East. at 40 chains set temporary 1/4 post and at 80 chains intersected our line on Town line. Then run from the 1/4 post on the north to the 1/4 post on the south, also from the East 1/4 post to that on the West and at the intersection of these lines the center post was planted



At 3, 5 and 7 were known corners
at 2 corner established from old B
at C Elm 7 S 26½ E 178 feet
Linden 12 N 18 W 3 feet
at 6 W oak 2 in N 24 W 24 feet