#52

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID : S1/4 Sec. 7, T18N-R1E

41801070020

DATE	CREW	MONUMENT TYPE ----------
October 25, 2017	Zachariah P.Dechant Gary L. Dechant	Existing Harrison Monument intact, set new sign 1' south At remnants of down fence corner.

References:	Bearing	Distance
1) Set 3/4"x24"round iron bar, down 4", 3' west of 5" White Pine	N22E	21.46'
2) Set 3/4"x24" round iron bar, down 4", 4' NW of 12" White Oak	S61E	15.93 '
3) Set 3/4"x24" round iron bar, down 4", 4' NE of 4" White Pine	S37W	16.68'
4) Set 3/4"x24" round iron bar, down 4", 3' SE of 3" Maple	N56W	23.00'

Gary L. Dechant

WISCONSIN
GARY L.
DECHANT
S-1744
CAMP
DOUGLAS, WI
LAND SURVEYOR

November 20, 2017

CERTIFICATE

I, William C. Jung, do hereby certify that on the seventh day of June 19 82, I found (evidence) ~~no evidence~~ of the North ¼ corner of Section 18, T 18 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 14th day of June 19 82.

William C. Jung - R. L. S. 1323

County Surveyor's Office
Title

Approved: HARLEY A. SIME
MONROE CO. SURVEYOR

COUNTY SURVEYOR FORM NO. 1

CERTIFIED LAND CORNER

No. 52

History of corner establishment since Original Government Survey

In October of 1969, Fred Zietlow found a well point at the occupied fence corner. Duke Marten shows an existing well point at this corner in his survey of January of 1974. Mark Heidecke shows an existing 2" iron pipe at this corner in his survey of June, 1980. It appears Marten and Heidecke had the same point.

Description of corner evidence found:

Found a 2¼"x30" iron pipe (well point) and replaced it with a Harrison monument.

See Reverse Side For Maintenance

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

William C. Jung

Witnesses to corner location:

William Jung

Bryan Meyer

WISCONSIN
WILLIAM C. JUNG
S-1323
TOMAH, WIS.
LAND SURVEYOR



All trees are double blazed with blazes facing the corner. They are also hacked in the side with a nail set in the hack. Distances are to the nails. All fences shown are down.



● = LOCATION CORNER

T 18 N R 1 E

WISCONSIN

SURVEY CONTROL ORDER

Horizontal	
Vertical	

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town of Byron

County of Monroe