83

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID : SE Sec.23, T17N-R1W

21701230000

DATE	CREW	MONUMENT TYPE ----------
November 12, 2018	Zachariah P.Dechant Gary L. Dechant	Found bottom section of broken up Harrison. Fit remaining 1981 bearing tree, Basswood 9.85' southeast. Replaced bottom section of Harrison with a 1¼"x7' round iron bar, up 1". West side of fence corner.

References:	Bearing	Distance
1) Set 3/4"x24" round iron bar, down 8"	N29E	20.29'
2) Set 3/4"x24" round iron bar, down 4"	S23E	19.55'
3) Set 3/4"x24" round iron bar, with flat stone	S10W	25.83'
4) Set 3/4"x24" round iron bar, down 3", 6' SE of 20" Black Cherry	N20W	35.92'

WISCONSIN
GARY L. DECHANT
S-1744
DOUGLAS, WI
LAND SURVEYOR

Gary L. DeChant

December 20, 2018

CERTIFICATE

I, Harley A. Sime, do hereby certify that on the 29th day of June 19 81, I found (evidence) (~~no evidence~~) of the SE corner of Section 23, T 17 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 25th day of August 19 81.

Harley A. Sime, R.L.S. 355

County Surveyor
Title

Approved: HARLEY A. SIME
MONROE CO. SURVEYOR

COUNTY SURVEYOR FORM NO. 1

CERTIFIED LAND CORNER

No. 83

History of corner establishment since Original Government Survey

No known recorded history since the original government survey.

Description of corner evidence found:

Accepted fence corner as best available evidence.

See Reverse Side
For Maintenance

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

B. Meyer

G. Dechant

(ALL TREES ARE DOUBLE BLAZED WITH NAIL & CAP SET)





SURVEY CONTROL ORDER

Horizontal	
Vertical	

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town Tomah

County of Monroe