



# U.S. Land Survey Monument Record

Corner ID: S¼ Sec. 5, T16N-R1E

41601050200

Type of Monument: Harrison Monument

Sec. 5, T16N-R1E



○ = 1-1/4" IRON PIPE, DOWN 8"

County Coordinates:

Witnesses: Zachariah P. Dechant  
Gary L. Dechant

Basis For Monument Location:

(Show info such as history, evidence, testimony, found or method of relocation)


Lawrence Feddersen set a 1¼" round iron bar at a fence corner on May 8, 1981 as shown in Vol 5 CSM P 30. Bryan Meyer replaced the 1¼" iron bar with a Harrison on October 20, 1983.

In 1995 I did survey work for Clayton Hansen as shown on Section summary dated October 25, 1995. It was then that we discovered that the 1¼" iron bar set by Feddersen was at a location that would significantly disrupt much occupation in Section 8. We also found old, down wire running south, 45° east, indicating there could have been a cow lane here at one time.

During conversation with Larry Feddersen, he stated he had not run the entire south line of Section 5 and relied on a scaled distance from a USGS map along the south l line. I relocated the corner and set a 1"x24" iron pipe in line with an existing east-west fence and half way between section corners, which fell 59' east of Feddersen's location. I contacted the County Surveyor and he stated that he would take care of moving the Harrison to my location.

Nov. 7, 2013, we found that the Harrison had not been moved and thus did move the Harrison in place of my 1" iron pipe and placed reference markers as shown below. I informed the land owner to the north, Elmer Pasch. He had no concerns or objections. This location best fits other occupational evidence throughout section 8. The only occupation affected in Section 5 is the north-south fence shown in Vol 5 CSM P 30. Instead of the north-south quarter line being 3' west of an existing fence, it will be approx. 5 east of the existing fence, still within reason.

Vol 17 CSM P17 was recently completed in the SW¼ of Section 8 which was based on my location of the S¼ corner of Section 5.



41601050020



I, Bryan H. Meyer, do hereby certify that on the 19<sup>th</sup> day of August 19 83, I found (evidence) ~~no evidence~~ of the South 1/4 corner of Section 5, T 16 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 20<sup>th</sup> day of Oct. 19 83.

Bryan H. Meyer  
Deputy County Surveyor  
Title

History of corner establishment since Original Government Survey  
Larry Fedderson was here in May of 1981 and set a 1 1/4" round iron bar.

Description of corner evidence found:

Found Mr. Fedderson's 1 1/4" round iron bar and replaced it with a Harrison monument.

**This corner location is under investigation. Please contact the Monroe County Surveyor at 608/427-3624 prior to using this corner location.  
Gary Dechant, Monroe County Surveyor**

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:



Crew: Meyer, Wilhite  
Date: August 19, 1983-12:30 P.M.  
Weather: Humid, P. Cloudy

Witnesses to corner location:

Bryan H. Meyer  
Dallas Wilhite

The trees shown are double blazed, with distances to a nail set in a hack in the side of each tree.

The bearings shown are hand compass bearings.



APPROVED: Harley A. Sime  
Monroe County Surveyor

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town of Clifton  
County of Monroe

I, Bryan H. Meyer, do hereby certify that on the 19<sup>th</sup> day of August 19 83, I found (evidence) ~~(no evidence)~~ of the South 1/4 corner of Section 5, T 16 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 20<sup>th</sup> day of Oct. 1983.

*Bryan H. Meyer*

Deputy County Surveyor

Title

History of corner establishment since Original Government Survey

Larry Fedderson was here in May of 1981 and set a 1 1/4" round iron bar.

Description of corner evidence found:

Found Mr. Fedderson's 1 1/4" round iron bar and replaced it with a Harrison monument.



COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Crew: Meyer, Wilhite  
Date: August 19, 1983-12:30 P.M.  
Weather: Humid, P. Cloudy



Witnesses to corner location:

Bryan H. Meyer

Dallas Wilhite

The trees shown are double blazed, with distances to a nail set in a hack in the side of each tree.

The bearings shown are hand compass bearings.



APPROVED: Harley A. Sime  
Monroe County Surveyor

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town of Clifton  
County of Monroe