

49


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : SE Sec.8, T17N-R1E
41701080000**

DATE	CREW	MONUMENT TYPE -----
May 4, 2017	Zachariah P.Dechant Gary L. Dechant	Existing 1½" iron pipe, up 1', 22' south of roadway Set sign 1' west

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6" in center of roadway	N44E	30.68'
2) Set 3/4"x24" round iron bar, down 6"	S70E	13.50'
3) Set 3/4"x24" round iron bar, down 6"	S80W	17.30'
4) Existing 1¼" iron pipe in center of roadway, lowered 6"	N54W	37.56' (37.63')



I, Bryan H. Meyer, do hereby certify that on the 16th day of August 19 91, I found (evidence) ~~(in evidence)~~ of the Northwest corner of Section 16, T 17 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 26th day of August 19 91.

Bryan H. Meyer
Deputy County Surveyor

History of corner establishment since Original Government Survey
It appears that Lenschow was here sometime in the 1950s or 1960s and set an iron pipe. A crew from the County Surveyor's Office found Lenschow's pipe and replaced it with a Harrison marker in April of 1975.

Description of corner evidence found:

This corner was re-established at point 109.5 feet westerly from the elm tree called for on the April 10th, 1975 tie sheet and at the recorded distance from the W 1/4 corner of said Sec. 16. (The Harrison Monument was found lying flat in the vicinity of this corner)

**Reverse Side
or Maintenance**



H. A. Sime and Associates
P. O. Box 705
Tomah, Wisconsin 54660
Phone: (608)-372-5392


COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Crew: Meyer, Kenworthy
Date: August 16, 1991
Weather: Overcast, Rainy, 80±.
Witnesses to corner location:


Bryan H. Meyer

John Kenworthy



**See Reverse Side
For Maintenance**

- = Set 2 1/2" x 7' iron pipe
 - = Set 1 1/4" x 24" iron pipe
- NOTE: Set sign 1/2' ± West of pipe.



● = LOCATION CORNER
T 17 N R 1 E
WISCONSIN

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town of Oakdale
County of Monroe

I, Harley A. Sime, do hereby certify that on the 10th day of April 19 75, I found (evidence) (~~no evidence~~) of the NW corner of Section 16, T 17 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 2nd day of Feb. 19 78.

Harley A. Sime
County Surveyor
Title

History of original corner establishment:

Description of corner evidence found:

Replaced Henry Lenschow 1" iron pipe he set as Section corner.

** See Revised Tie Sheet*



**Approved: HARLEY A. SIME
MONROE CO. SURVEYOR**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Replaced pipe with a Harrison marker.

Witnesses to corner location:

L. Fedderson
K. Pritzlaff



O = LOCATION CORNER
T 17 N R 1 E
WISCONSIN

**See Reverse Side
For Maintenance**

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Oakdale

County of Monroe

COUNTY SURVEYOR FORM NO. 1