

CERTIFICATE

CERTIFIED LAND CORNER

No. 30

41801050020

I, Harley A. Sime, do hereby certify that on the 4th day of June 1980, I found (evidence) (~~no evidence~~) of the N 1/4 corner of Section 8, T 18 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 26th day of Feb. 1981.

Harley A. Sime, R.L.S. 355

County Surveyor
Title

History of corner establishment since Original Government Survey

Schroeder (?) was at this corner in September of 1895. Bergman set an angle iron at this corner in July of 1954. Pritzlaff set a R.R. spike at the occupied corner in April of 1975.

Description of corner evidence found:


Found a R.R. spike used in previous survey work. Removed the R.R. spike and replaced it with a 1 1/4" iron bar. This location fits Bergman's distance back to the N.W. corner of Section 8 and also falls in the road as is shown on Bergman's map.

COUNTY SURVEYOR FORM NO. 1



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

M. Scott Sowers
T. Tormoen
C. Dade



Replaced R.R. spike with 1 1/4" iron bar



• = LOCATION CORNER

T 18 N R 1 E

WISCONSIN

Approved: HARLEY A. SIME
MONROE CO. SURVEYOR

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

SIGN PLACED 12/22/86
Kenworthy

~~City, Village~~ Town Byron

County of Monroe