

CERTIFIED LAND CORNER

No. 43

Corner No. 41801110000

CERTIFICATE

I, Bryan H. Meyer, do hereby certify that on the 4th day of January, 2006, I found (evidence) ~~(no evidence)~~ of the Northeast corner of Section 14, T 18 N, R 1 E Fourth principle Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 19th day of February, 2008

Registered Land Surveyor

Title

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner.

Witnesses to corner location:

Bryan H. Meyer

Jerry Hibbard

SURVEY CONTROL ORDER

Horizontal
Vertical

MONROE COUNTY COORDINATE SYSTEM

Corner	Northing	Easting	Elevation
Control Station Name			

History of corner establishment since Original Government Survey


Schroeder was at this corner in December of 1889. Fred Zietlow set an iron bar at this corner in July of 1970. Harley Sime had the bar replaced with a Harrison marker in June of 1980. James Carroll was here as shown on his July, 1985 Plat of Survey.

UPDATE:

The County Surveyor's Office was notified by the Town of Byron that a road resurfacing project was to take place. This corner was referenced out. Following resurfacing, this corner was reset with a railroad spike and new ties were taken as shown.


Set railroad spike at corner location. Metal detector indicates that the Harrison marker is still in. It is unknown how much of marker is still there and at what depth.

- ▲ = Set railroad spike
- = Existing 3/4" iron bar
- = Set 3/4" x 18" round iron bar



Bryan H. Meyer, Registered Land Surveyor
H. A. Sime and Associates, P. O. Box 50
Tomah, Wisconsin 54660 * 608-372-5392

Section 14



O = Corner Location
T 18 N R 1 E
WISCONSIN

~~City, Village or~~ Town of Byron

County of Monroe