

CERTIFICATE

I, Lawrence A. Feddersen, do hereby certify that on the 2 day of December 1977, I found (evidence) ~~(XXXXXX)~~ of the E 1/4 corner of Section 34, T 18 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 2 day of Dec. 1977.

Lawrence A. Feddersen

Registered Land Surveyor
Title

CERTIFIED LAND CORNER

No. 118

41801342000

History of original corner establishment:

No previous recorded history other than the original government survey record.

Description of corner evidence found:



An unrecorded 3/4"x24" iron bar set by Duane A. Marten was found at the intersection of fences North-South & East-West, and was replaced with a Harrison monument. The Harrison monument at the E 1/4 corner, an unrecorded grader blade bar at the NE corner of the SE 1/4-NE 1/4, and an unrecorded king bolt at the NE corner of Sec. 34, all fall on a straight line, with the grader blade falling half-way between the E 1/4 corner and the NE corner of Sec. 34. (SEE NOTE, BACK SIDE.)

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

nail/washer in power pole

Witnesses to corner location:

- Lawrence Feddersen
- Mark Heidecke
- Douglas Malliet



T 17 N R 1 E
18
WISCONSIN

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

PLACED
COUNTY SURVEYOR'S
SIGN 5-17-87

~~City or Village or Town~~ of Byron
County of Monroe

COUNTY SURVEYOR FORM NO. 1

NOTE: There is a Harrison monument 6.88' South & 1.80' East of the
king bolt at the NE corner of Section 34.