

U.S. LAND CORNER MAINTENANCE

Corner ID : S1/4 Sec.31 , T17N-R1W
21701310020

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
June 28, 2013	Zachariah P. Dechant Gary L. Dechant	Existing cast iron Harrison approx. 700' east of CTH "M", 30' south drive Set survey sign 1' north

References:

Set 3/4" hexagon iron bar, down 10", north side gravel drive
Set 3/4" hexagon iron, down 14" north side of field
Set 3/4" hexagon iron bar, down 12" in hay field
Existing 3/4" iron bar, in east-west fence

<u>Bearing</u>	<u>Distance</u>
N32W	41.59'
S82E	39.04'
S34W	22.38'
East	24.90'



June 28, 2013

21701310020

I, Garold A. Sime, do hereby certify that on the 26th day of May 1983, I found ~~(evidence)~~ (no evidence) of the N¹/₄ corner of Section 6, T 16 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 19 day of Jan. 1984.

Garold A. Sime
Deputy County Surveyor
Title

History of corner establishment since Original Government Survey

Fred Holden was at this corner in April 1907





Description of corner evidence found:

Set this corner at the intersection of the existing East - West fence line with the North - South Quarter line which is established by existing corners at the S¹/₄ corner & C¹/₄ corner.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Garold A. Sime
Dallas Wilhite



Approved: **HARLEY A. SIME**
MONROE CO. SURVEYOR

SURVEY CONTROL ORDER

Horizontal _____
Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village~~ or Town Wilton
County of Monroe

COUNTY SURVEYOR FORM NO. 1