

125


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : SE Sec. 34, T17N-R1W
21701340000**

DATE	CREW	MONUMENT TYPE -----
November 5, 2015	Zachariah P.Dechant Gary L. Dechant	Replaced old broken Harrison with new TCP Marker at fence corner in stone pile, sign 1.5' NE

References:

	Bearing	Distance
1) Set 3/4"x24" round iron bar, down 6", 4' SE of 2'x3" stone	N58E	21.51'
2) Set 3/4"x24" round iron bar, down 6", 5' east of fence, two stones over bar	S14E	27.61'
3) Set 3/4"x24" round iron bar, down 6", 8' NE of Double 14" White Oak	S57W	32.22'
4) Set 3/4"x24" round iron bar, down 6"	N46W	22.20'



I, Harley A. Sime, do hereby certify that on the 13th day of February 1981, I found (evidence) ~~(see evidence)~~ of the SE corner of Section 34, T 17 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 16th day of Feb. 1981.

Harley A. Sime, R.L.S. 355

County Surveyor
Title

History of corner establishment since Original Government Survey

No known recorded history since the original government survey.

Description of corner evidence found:

Accepted a 4-way fence corner as best available evidence as it also fits other field evidence well.

See Reverse Side For Maintenance



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Dechant-Crew Chief

B. Meyer

C. Pietz



T 17 N R 1 W
WISCONSIN

(All trees are double blazed with N&C's set)

**Approved: HARLEY A. SIME
MONROE CO. SURVEYOR**

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town Tomah
County of Monroe

COUNTY SURVEYOR FORM NO. 1