

126

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID : S1/4 Sec.34, T17N-R1W

21701340020


<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
April 10, 2014	Zachariah P.Dechant Gary L. Dechant	Corner destroyed, reset from previous surveys. Ties gone or in bad condition. Set Railroad spike centerline road

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" hexagon iron bar, down 16" in field	N19E	42.99'
2) Set 3/4"x24" hexagon iron bar, down 10", edge of field	S14E	45.54'
3) Set 3/4"x24" hex iron bar, down 16", in field	S19W	49.57'
4) Set 3/4"x24" hex iron bar, down 14" in field	N14W	37.82'

COORDINATES:

NOTE: Reference markers and Railroad spike (S1/4)
set on straight lines



CERTIFICATE

CERTIFIED LAND CORNER

No. 6

21701340020

I, Harley A. Sime, do hereby certify that on the 23rd day of July 1979, I found (evidence) ~~(no evidence)~~ of the North 1/4 corner of Section 3, T 16 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of corner establishment since Original Government Survey
No known history since the original government survey.

Dated this 7th day of April 1980.
Harley A. Sime, R.L.S. 355

Description of corner evidence found:

Fred Zietlow set an iron bar at this corner in September of 1970. Found iron bar and replaced it with a Harrison Monument.

County Surveyor



Title

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Meyer
Dade



Approved: HARLEY A. SIME
MONROE CO. SURVEYOR

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

SIGN PLACED 12/24/86
Kenworthy, Set sign 25 1/2' ±
North of corner.

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

Wilton or Town
County of Monroe