

120

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


Corner ID : E1/4 Sec36, T17N-R1W

21701362000

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u>
September 23, 2016	Zachariah P. Dechant Gary L. Dechant	Corner destroyed during road construction, Reset corner from two remaining bearing trees. S72E, 23.57' 10" Hickory and SE, 13.19' 10" White Oak Reset corner with 1 1/4"x30" round iron bar, down 5". Now falls in relocated Town Road, Irvine Road. Set new sign SE 10' on east side large boulder

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6"	N80E	40.10'
2) Set 3/4"x24" round iron bar, down 6",	S64E	22.45'
3) Set 3/4"x24" round iron bar, down 6"	S38E	27.01'
4) Set 3/4"x24" round iron bar, down 6"	S10W	31.08'



CERTIFICATE

I, Bryan H. Meyer, do hereby certify that on the 28th day of February, 2006, I found (evidence) ~~(no evidence)~~ of the East 1/4 corner of Section 36, T 17 N, R 1 W Fourth principle Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 16th day of March, 2006

Bryan H. Meyer
 Registered Land Surveyor
 Title

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner.

Witnesses to corner location:


Bryan H. Meyer
Mitchell Sime

SURVEY CONTROL ORDER

Horizontal
Vertical

MONROE COUNTY COORDINATE SYSTEM				
Corner	Northing	Easting	Elevation	
Control Station Name				

⊕ = Existing cast iron Harrison marker
 ○ = Set 3/4"x18" round iron bar



NOTE: Set sign and post Southeast of corner.

NOTE: The three trees shown are double blazed with the blazes facing the corner; the distances shown are to a nail set in a hack in the side of each tree.

CERTIFIED LAND CORNER

History of corner establishment since Original Government Survey

Since this corner was re-established by Larry Feddersen in June of 1982, it has been used by Dwayne Hefner as shown in Certified Survey Maps dated 2/25/02; 12/10/02 and 4/28/03. I found this Harrison down 4" and in need of maintenance. I was able to confirm one remaining tie and aquired three new ties as shown.


See Reverse Side For Maintenance

No. 120(2)



Bryan H. Meyer
 H. A. Sime and Associates
 P. O. Box 50
 Tomah, Wisconsin 54660
 Phone: 608-372-5392

Section 36



O = Corner Location

T 17 N R 1 W
 WISCONSIN

Town of Tomah

County of Monroe

I, Lawrence A. Feddersen, do hereby certify that on the 24 day of June 1982, I found ~~(evidence)~~ (no evidence) of the E $\frac{1}{4}$ corner of Section 36, T 17 N, R 1W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 24 day of June 1982.

Lawrence A. Feddersen

Registered Land Surveyor
Title

History of corner establishment since Original Government Survey

No known history of corner establishment since Original Government Survey.

**See Reverse Side
For Maintenance**

Description of corner evidence found:

Set in North-South fence line and at proportionate distances from the E $\frac{1}{4}$ Section 1, T16N - R1W. to the E $\frac{1}{4}$ corner of Section 25 T17N-R1W. According to a Mr. Bethhauser, an adjacent land owner, he does recall an old fence corner once standing near the set Harrison before the road was put in.


COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:


Witnesses to corner location:

Gary Dechant (D)

Thomas Mangene



All trees doubled blazed, nail/washer in side of trees, scribed, distance to nail/washer



**Approved: HARLEY A. SIME
MONROE CO. SURVEYOR**

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town OF TOMAH
County of MONROE