

67

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : SE Sec. 16, T18N-R2W
21802160000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
November 4, 2016	Zachariah P.Dechant Gary L. Dechant	Existing Harrison intact on NE slope, west of fence corner. Pit 3' SE not SW. Harrison is facing west not north. Let's blame David E. Madison !

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6", 19' SW of 8" White Pine	N38E	18.75'
2) Set 3/4"x24" round iron bar, down 6", 3' west of fence	S20E	18.65'
3) Set 3/4"x24" round iron bar, down 6", 7' NE 20" Black Oak (BT)	S53W	23.50'
4) Set 3/4"x24" round iron bar, down 6", 4' SE 16" Black Oak (BT)	N70W	25.64'



CERTIFICATE

I, Nicholas M. Hillmer, do hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Wisconsin.

Dated this 23rd day of May, 2013



Nicholas M. Hillmer, P.L.S. 2909
Anderson Engineering of Minnesota, LLC.

CERTIFIED LAND CORNER


History of corner established since Original Government Survey

In December of 1987, Gary Dechant found the remains of a rotted fence corner. Dechant accepted this as the best available evidence and set a Harrison monument.

Description of evidence found

On January 24th, 2013, Anderson Engineering of Minnesota located the Harrison monument 0.3 feet above grade and 0.4 feet south of a witness post with a survey marker sign.

No. 67
21802160000



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Nick Hillmer
Josh Oslund
Dan Greenwald





MONROE COUNTY
COORDINATE SYSTEM
NAD 1983 (2007)

HARRISON MONUMENT
Northing (Y) 410706.85
Easting (X) 678646.32

Base Station - 22 182W
Northing (Y) 408053.25
Easting (X) 679287.00

All distances are shown in U.S. Survey Feet.
Ties are to 60D nails set in trees.
Bearings are for tie reference purposes only.
Coordinates were derived from RTK GNSS procedures.



⊙ = LOCATION CORNER
Corner I.D. SE 16
T 18 N R 2 W
Town of Greenfield
Monroe County, WI.

**See Reverse Side
For Maintenance**

I, Gary L. Dechant, do hereby certify that on the 30th day of December 19 87, I found (evidence) (~~no evidence~~) of the NE corner of Section 21, T 18 N, R 2 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 31st day of Dec. 1987.

Gary L. Dechant
Registered Land Surveyor, 1744
Title


History of corner establishment since Original Government Survey

No known recorded history since original government survey.

Description of corner evidence found:

Accepted remains of rotted fence corner as best available evidence.

**See Reverse Side
For Maintenance**





Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

David E. Madison

Gary L. Dechant



(Trees double blazed with N&C's set.) WISCONSIN

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Greenfield
County of Monroe

COUNTY SURVEYOR FORM NO. 1