

CERTIFICATE

I, Nicholas M. Hillmer, do hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Wisconsin.

Dated this 23rd day of May, 2013



Nicholas M. Hillmer, P.L.S. 2909
Anderson Engineering of Minnesota, LLC.

CERTIFIED LAND CORNER

History of corner established since Original Government Survey

Fred A. Holden was here in September of 1911 and calls for an "iron stake." Bryan H. Meyer was here in July of 1983 and talked with Mr. Leroy Frost, a local land owner. Mr. Frost told Meyer he removed a 1 1/2 inch iron pipe when he enlarged his field. Meyer visited Mr. Frost again in 1990 and Mr. Frost showed Meyer the approximate location of where the pipe was. Mr. Frost then showed Meyer the forty corners to the east (old buggy axle) and south (3/4 inch iron rod). Meyer set a Harrison monument by doubling north the bearing and distance of the line that runs along the east line of Section 4. This point is on line with an existing fence to the east and also agrees with Holden's forty corner to the east extremely well.

No. _____
21802042000

Description of evidence found

On March 12th, 2013, Anderson Engineering of Minnesota located the Harrison monument with the top broke off. The mark is 15 inches below grade and 1.55 feet southeast of the fence corner.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Nick Hillmer
Josh Oslund
Dan Greenwald





MONROE COUNTY
COORDINATE SYSTEM
NAD 1983 (2007)

HARRISON MONUMENT
Northing (Y) 423842.78
Easting (X) 678554.19


Base Station - 22 182W
Northing (Y) 408053.25
Easting (X) 679287.00

All distances are shown in U.S. Survey Feet.
Ties are to 60D nails set in trees.
Bearings are for tie reference purposes only.
Coordinates were derived from RTK GNSS procedures.



⊙ = LOCATION CORNER
Corner I.D. E 1/4 4
T 18 N R 2 W
Town of Greenfield
Monroe County, WI.

21802042000



H. A. Sime and Associates
P. O. Box 705
Tomah, Wisconsin 54660
Phone: (608)-372-5392

I, Bryan H. Meyer, do hereby certify that on the 11th day of October, 19 90, I found (no evidence) of the West 1/4 corner of Section 3, T 18 N, R 2 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 26th day of Dec., 19 90.

Bryan H. Meyer
Deputy County Surveyor

History of corner establishment since Original Government Survey

Fred A. Holden was here in September of 1911 and calls for an "iron stake".

Description of corner evidence found:

I was here in July of 1983 and talked to Mr. LeRoy Frost, a local landowner. He told me that he removed a 1 1/2" iron pipe when he enlarged his field. I again visited with Mr. Frost in October of 1990. He showed me the approximate location of where the pipe was. He then showed me the forty corners to the East (old buggy axel) and South (3/4" iron rod). I set this corner by doubling North the bearing and distance of the line that runs along the West line of the SW 1/4-SW 1/4. This point is on line with an existing fence to the East. It also agrees with what Holden would have had to the forty corner to the East extremely well.

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Crew: Meyer, Kenworthy
Date: October 11, 1990
Weather: Clear, Snow cover, 40°±
Witnesses to corner location:

John Kenworthy

Bryan H. Meyer


NOTE: The bearings shown hereon are magnetic hand compass bearings.

OPEN

Set cast iron Harrison marker, down 6"± in hay field. Set sign 21'± East.



NOTE: The four trees shown are double blazed; the distance to each is to a nail set in a hack in the side of each tree.

FIELD



Drawing by John Kenworthy

NOTE: The fences shown are in poor condition.



SURVEY CONTROL ORDER

Horizontal _____
Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City/Village~~ Town of Greenfield
County of Monroe