

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

35

Corner ID: E1/4 Sec. 7, T17N-R3W
21703072000

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT INFO</u>	<u>Bearing</u>	<u>Distance</u>
February 28, 2020	Zachariah P. Dechant Gary L. Dechant	Existing Harrison, top broke off, down 8", signs 1' north & 1' east		
1) Set 3/4"x24" round iron bar, along south bank of southerly sediment pond			East	34.64'
2) Set 3/4"x24" round iron bar, south side of trail			S36E	47.40'
3) Existing 3/4" round iron bar, south side of trail			South	40.64'
4) Set 3/4"x24" round iron bar, along south bank of southerly sediment pond			West	38.30'

Gary L. Dechant
WISCONSIN
GARY L.
DECHANT
S-1744
DOUGLAS, WI
LAND SURVEYOR
March 3, 2020

CERTIFICATE

I, Bryan H. Meyer, do hereby certify that on the 4th day of October, 2005, I found evidence of the East 1/4 corner of Section 7, T 17 N, R 3 W Fourth principle Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 1st day of March, 2007

[Signature]

Registered Land Surveyor

Title

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner.

Witnesses to corner location:

Bryan H. Meyer

Steve Gerke

SURVEY CONTROL ORDER

Horizontal

Vertical

Corner	Northing	Easting	Elevation	
Control Station Name				

CERTIFIED LAND CORNER


History of corner establishment since Original Government Survey

Perry-Carrington Engineering from Marshfield, Wisconsin, performed work in this area on the old Sparta Airport and visited this corner as shown on a piece on an unrecorded, undated map. A crew from H. A. Sime and Associates found a pipe at this corner and replaced it with a Harrison marker in August of 1977.

Description of corner evidence found:

Found Harrison marker, set a sign and gathered additional ties as shown below.

See Reverse Side For Maintenance



- ⊙ = Existing cast iron Harrison marker
- = Existing 3/4" round iron bar
- = Set 3/4" x 18" round iron bar

MONROE COUNTY COORDINATE SYSTEM

No. 35
Page 2



Bryan H. Meyer
H. A. Sime and Associates
P. O. Box 50
Tomah, Wisconsin 54660
Phone: 608-372-5392

Section 7



O = Corner Location
T 17 N R 3 W
WISCONSIN

Town of ANGELO

County of MONROE

I, Harley A. Sime, do hereby certify that on the 1st day of August 19 77, I found (evidence) ~~(no evidence)~~ of the E 1/4 corner of Section 7, T 17 N, R 3 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 1st day of March 19 78.

History of original corner establishment:

None

See Reverse Side For Maintenance

Description of corner evidence found:

Found an iron pipe that had been used in several previous surveys. Replaced the pipe with a Harrison marker.

County Surveyor
Title

**Approved: HARLEY A. SIME
MONROE CO. SURVEYOR**


Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:



C. Pietz - Crew Chief

B. Meyer

D. Dade



COUNTY SURVEYOR FORM NO. 1



O = LOCATION CORNER

T 17 N R 3 W

WISCONSIN

**SIGN PLACED 11/24/86
Meyer, Kenworthy**

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Angelo

County of Monroe