


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

30

**Corner ID: S1/4 Sec. 5, T17N-R3W
21703050020**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT INFO</u>
May 19, 2020	Zachariah P. Dechant Gary L. Dechant	Existing Harrison, top broke off, down 6", 16.5' south of center of Goodwater Ave

	<u>Compass Bearing</u>	<u>Distance</u>
1) Existing pinched 1" iron pipe at wooded fence corner post (1975 tie)	North	49.38 (49.47)
2) Set 3/4"x24" round iron bar, down 6", 4' NW of 8"-6" double White Oak	S10E	41.45
3) Set 3/4"x24" round iron bar, down 6", 4' NE of 18" White Pine (1975 BT)	S16W	38.26'
4) Set 3/4"x24" round iron bar, down 6", 3' north of address sign, 11773 Goodwater	S63W	62.63'
5) Existing 3/4" round iron bar, 1' west of wooded fence corner post, on property line between 11776 and 11782 Goodwater Ave	N56W	78.79'

Zachariah P. Dechant

May 19, 2020

I, Harley A. Sime, do hereby certify that on the 17th day of July 19 75, I found (evidence) ~~(no evidence)~~ of the South 1/4 corner of Section 5, T 17 N, R 3 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 8th day of April 1977.

County Surveyor
Title

History of original corner establishment:
Fred A. Holden was here in April, 1907.

Description of corner evidence found:
Ran out the section and the existing irons agreed.
Replaced 1 1/2" iron pipe with Harrison.

3/12/81
The ex. I.P. was set by Bergman in January of 1933. *WCS*

See Reverse Side
For Maintenance

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set Harrison monument flush.



Witnesses to corner location:

Pritzlaff

Pietz

Note: The top portion of the Harrison Monument was broke off and 3 of the original ties had been destroyed. I took 180° 32' new ties to the broke off monument.

Trees are double blazed and dist. are to a nail set in a hack in the side of the tree.



Crew: Garold A. Sime
Monroe County Surveyor Dated: November 28th, 1989

John Kenworthy
Brian Forsythe
WISCONSIN COORDINATE SYSTEM

SURVEY CONTROL ORDER

Horizontal				
Vertical				
Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Angelo

County of Monroe

I, Harley A. Sime, do hereby certify that on the 17th day of July 1975, I found (evidence) ~~(no evidence)~~ of the South 1/4 corner of Section 5, T 17 N, R 3 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 8th day of April 1977

History of original corner establishment:
Fred A. Holden was here in April, 1907.

**See Reverse Side
 For Maintenance**

Description of corner evidence found:
Ran out the section and the existing irons agreed.
Replaced 1 1/2" iron pipe with Harrison.

County Surveyor

Approved: HARLEY A. SIME
MONROE CO. SURVEYOR

3/12/81
The existing iron pipe was set by Bergman in January of 1933.



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set Harrison monument flush.

Witnesses to corner location:

Pritzlaff

Pietz



SURVEY CONTROL ORDER

Horizontal _____

Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Angelo

County of Monroe

COUNTY SURVEYOR FORM NO. 1