

71


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : SE Sec.18, T17N-R1E
41701180000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u>
September 11, 2014	Zachariah P. Dechant Gary L. Dechant	Existing Harrison in tact, down 8", 27' east of driveway fire no. 29019, 42' south of CTH "C".

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" iron bar, down 6", 7' SE of power pole	N61E	64.97'
2) Set 3/4"x24" iron bar, 3' north of wood fence, down 6"	East	34.69'
3) Set 3/4"x24" iron bar, down 6", in lawn west of driveway	S51W	46.94'
4) Set 3/4"x24" iron bar, down 10", west side of field entrance	NW	79.95'

Gary L. Dechant

September 11, 2014

I, Lawrence A. Feddersen, do hereby certify that on the 10th day of August 19 78, I found (evidence) ~~(NO EVIDENCE)~~ of the Southeast corner of Section 18, T 17 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 13 day of Sept. 19 78.

Lawrence A. Feddersen

REGISTERED LAND SURVEYOR S-1226
Title

History of original corner establishment:



Found a 3/4"x24" round iron bar set by H.A. Sime & Asso. in July, 1977. we also found an old 1"x24" iron ^{PIPE} of unknown origin, N00°59'04"E, 0.54' from the iron bar. Eldon Brown, upon whose land this corner is located, indicated to us that the iron pipe has been used as the corner for a number of years by different surveyors. We did not find, however, any recorded maps of any survey tied to this Description of corner evidence found: corner.

We accepted the iron pipe as being the corner, because it was clear that the pipe has, in fact, been in the ground for a long duration of time; and because it has been presumed to be the corner for a number of years by Eldon Brown and others as he indicated to us.

See Reverse Side For Maintenance

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:
Lawrence A. Feddersen
Douglas J. Malliet
Steve Towne
Dale Feddersen



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

SIGN PLACED 11/19/86 E.M. Mayer, Kenworthy

~~City/Village~~ Town of OAKDALE
 County of MONROE

COUNTY SURVEYOR FORM NO. 1