

132

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

Corner ID : S1/4 Sec. 31, T17N-R1E

41701310020

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u>
September 23, 2016	Zachariah P. Dechant Gary L. Dechant	Existing Harrison intact 9' east of driveway, down 14" All ties destroyed

References:

	<u>Bearing</u>	<u>Distance</u>
1) Existing 3/4" round iron bar leaning, reset down 6"	East	26.47' (26.50')
2) Set 3/4"x24" round iron bar, down 6", 8' north of sign	S28W	47.02'
3) Set 3/4"x24" round iron bar, down 6", 8' south of new fence corner	West	57.02'
4) Set 3/4"x24" round iron bar, down 6"	N30E	30.37'

Harrison and reference markers 1 & 3 set on straight line.



I, Harley A. Sime, do hereby certify that on the 22nd day of August 1972, I found (evidence) ~~(no evidence)~~ of the S 1/4 corner of Section 31, T17 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 2nd day of Feb. 1978.

Harley A. Sime
County Surveyor
Title

History of original corner establishment:

**Approved: HARLEY A. SIME
MONROE CO. SURVEYOR**

Description of corner evidence found:



Accepted intersection of existing fences as the best available evidence.

**See Reverse Side
For Maintenance**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

D. Marten
G. Sime



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Oakdale
County of Monroe

COUNTY SURVEYOR FORM NO. 1