

41801030000

I, Harley A. Sime, do hereby certify that on the third day of June 1980, I found (evidence) (~~removed~~) of the Southeast corner of Section 3, T18 N, R1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 26th day of Feb. 1981.

Harley A. Sime - R.L.S. 355

County Surveyor-Monroe County, Wisconsin
Title

History of corner establishment since Original Government Survey
Holden found the original corner in October of 1907. In his notes of his survey done during the 1930's, Kennedy shows the corner as being in the road centerline. Harley Sime shows an iron pipe at this corner in his notes of July, 1964. Duane Marten used this iron pipe in his survey of August, 1969. Zietlow used this corner in July of 1970. Bergman mentions an unrecorded stone at this corner in his survey of July, 1954. The old town road records show

Description of corner evidence found: this corner to be at the road intersection. Found a R.R. spike set over an iron pipe. This location had been used in previous survey work. Removed the spike and pipe and replaced them with a Harrison. The stone was not found. This location fits Bergman's notes extremely well.



COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

- Scott Sowers
- Todd Tormoen
- Chuck Dade

**Approved: HARLEY A. SIME
MONROE CO. SURVEYOR**



T 18 N R 1 E

WISCONSIN

PLACED
COUNTY SURVEYOR'S
SIGN

SIGN PLACED 12/22/86
Kenworthy

~~City, Village~~ Town of Byron Replaced 6-17-89

County of Monroe
Wisconsin

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				