

I, William C. Jung, do hereby certify that on the 7th day of August 1981, I found (evidence) ~~the evidence~~ of the Northeast corner of Section 18, T18 N, R1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 28th day of August 1981.

William C. Jung

Registered Land Surveyor

Title

William C. Jung

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Gary Dechant

Carlton Pietz




Approved: HARLEY A. SIME MONROE CO. SURVEYOR


History of original corner establishment: In October of 1940, Ray Hurlburt set an Iron Pipe at the corner and set a torque tube 33 feet to the West. He found evidence of a previous corner where he set the iron pipe. The previous corner was probably set or found by a surveyor in September of 1895. Harley Sime found this corner again in about 1966. Fred Zietlow used this corner in October of 1969 and again in July of 1970. Pritzlaff used this corner in April of 1975. Description of corner evidence found:

Found bolt over iron pipe. Removed both and set a Harrison marker.

UPDATE: Found Cast Iron Harrison Monument (down 3") in pavement, obtained new ties as shown below.



Set chiseled x on 1st full rib on S. end of culvert WISCONSIN COORDINATE SYSTEM



SURVEY CONTROL ORDER

Table with 2 rows: Horizontal, Vertical

Table with 5 columns: Corner, East (X), North (Y), Elevation (Z), Zone

Village of Byron, County of Monroe, Wisconsin

CERTIFICATE

CERTIFIED LAND CORNER

No. 51
See Pg. 2

I, William C. Jung, do hereby certify that on the 7th day of August 1981, I found (evidence) ~~(no evidence)~~ of the Northeast corner of Section 18, T18 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment: In October of 1940, Ray Hurlburt set an Iron Pipe at the corner and set a torque tube 33 feet to the West. He found evidence of a previous corner where he set the iron pipe. The previous corner was probably set or found by a surveyor in September of 1895. Harley Sime found this corner again in about 1966. Fred Zietlow used this corner in October of 1969 and again in July of 1970. Pritzlaff used this corner in April of 1975.
Description of corner evidence found:

Dated this 28th day of August 1981.

Found bolt over iron pipe. Removed both and set a Harrison marker.

William C. Jung

Registered Land Surveyor

Title



William C. Jung

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Gary Dechant

Carlton Pietz



T 18 N R 1 E
WISCONSIN

COUNTY SURVEYOR FORM NO. 1

Approved: **HARLEY A. SIME**
MONROE CO. SURVEYOR

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

SIGN PLACED 12/20/86
Kenworthy

~~City, Village or~~ Town Byron
County of Monroe
Wisconsin