

# 48

**U.S. PUBLIC LAND CORNER  
MAINTENANCE**

**Corner ID : S1/4 Sec. 9, T18N-R1E**

**41801090020**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE -----</u>
July 6, 2016	Zachariah P. Dechant Gary L. Dechant	Existing Harrison intact, center line Copper Road 29' north driveway fire no. 8995 Copper Rd, down 5".

<u>References:</u>	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6", 4' south of 18" White Oak in lawn	N46E	77.17'
2) Set 3/4"x24" round iron bar, down 6",	S45E	60.31'
3) Set 3/4"x24" round iron bar, down 6", center driveway 8995 Copper Rd	S46W	59.32'
4) Set 3/4"x24" round iron bar, down 6", south side of ditch of cranberry beds 14' west of concrete culvert in ditch	N45W	123.52'

Harrison and reference monuments set on straight lines.



I, Harley A. Sime, do hereby certify that on the 3rd day of October 1973, I found ~~(evidence)~~ (no evidence) of the S 1/4 corner of Section 9, T 18 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

**See Reverse Side For Maintenance**

Description of corner evidence found:

Dated this 6th day of Feb. 1978.

Traversed Section 9 and set corner. There is also a 3/4" iron bar 78.67 feet North of the corner.



County Surveyor **Approved: HARLEY A. SIME**  
**MONROE CO. SURVEYOR**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set a Harrison marker.

Witnesses to corner location:

D. Marten  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



**PLACED COUNTY SURVEYOR'S SIGN 6-19-87**

O = LOCATION CORNER  
T 18 N R 1 E  
WISCONSIN

COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Byron

County of Monroe