

87

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : SE Sec. 21, T17N-R1W
21701210000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
October 27, 2016	Zachariah P. Dechant Gary L. Dechant	Existing Harrison top broke off, down 4" . 10' south of center line Hockey Avenue. 15' east center line of driveway 24988 Hockey Ave

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6", 11' north of telephone ped	N20E	58.72'
2) Set 3/4"x24" round iron bar, down 6"	S47E	33.36'
3) Set 3/4"x24" round iron bar, down 6", 4' west of 28" Box Elder	S13W	39.66'
4) Set 3/4"x24" round iron bar, down 6", 2' west of driveway	N37W	54.32'
5) Existing 1" iron pipe	South	23.02'



I, William C. Jung, do hereby certify that on the 21st day of June 19 78, I found (evidence) (~~no evidence~~) of the N.E. 17 corner of Section 28, T. 17 N, R. 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 16th day of Aug, 1978.

William C. Jung, R.L.S. 1323

Crew Chief, County Surveyor's
Title Office

History of original corner establishment:

None

Description of corner evidence found:

(Set by Marten)
 Found a 3/4" I.B. used in previous surveys and replaced it with a Harrison marker. There is also a 1 1/4" I.B. 50.33 feet north of the Harrison.

See Reverse Side For Maintenance



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Dechant

B. Meyer

(All trees double blazed with N&Cs set)



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

Approved by: Harley A. Sime
 County Surveyor

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Tomah

County of Monroe

COUNTY SURVEYOR FORM NO. 1