

118

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : E1/4 Sec. 34, T17N-R1W
21701342000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
November 5, 2015	Zachariah P.Dechant Gary L. Dechant	Existing Harrison intact, 230 NE of tower 6' west of fence, down 8", set sign 1' east

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" hex iron bar, down 10", west side of east cow lane fence	N65E	23.66'
2) Set 3/4"x24" hex iron bar, down 10" west side of east cow lane fence	S40E	31.31'
3) Set 3/4"x24" hex iron bar, down 12" in field	S35W	20.89'
4) Set 3/4"x24" hex iron bar, down 8", 6' SE of 14" Shagbark Hickory (BT)	N10W	33.94'



I, Harley A. Sime, do hereby certify that on the 13th day of February 1981, I found ~~(evidence)~~ (no evidence) of the E¹/₄ corner of Section 34, T17 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 16th day of Feb. 1981.

Harley A. Sime, R.L.S. 355

 County Surveyor
Title

History of corner establishment since Original Government Survey

No known recorded history since the original government survey.

Description of corner evidence found:

Set by single proportionate measurement. Fits other field evidence reasonably well.

**See Reverse Side
For Maintenance**

COUNTY SURVEYOR FORM NO. 1



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Dechant

B. Meyer

C. Pietz



**Approved: HARLEY A. SIME
MONROE CO. SURVEYOR**

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town Tomah
 County of Monroe