

99

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

Corner ID : E1/4 Sec.26, T17N-R2W


21702262000

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE -----</u>
October 3, 2014	Zachariah P.Dechant Gary L. Dechant	Found Harrison in tact 14' west of Hemlock Road, down 12". 163' north of driveway fire no. 17531.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" square iron bar, down 14" in field	N61E	57.75'
2) Set 3/4"x24" square iron bar, down 14: in field	S56E	63.30'
3) Set 3/4"x24" square iron bar, down 8" in grass trail	S61W	25.62'
4) Set 3/4"x24" square iron bar, down 8"	N56W	39.72'

Reference markers set on straight lines with Harrison.



I, Harley A. Sime, do hereby certify that on the 16th day of April 1976, I found ~~(evidence)~~ (no evidence) of the East 1/4 corner of Section 26, T 17 N, R 2 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 5th day of April 1977.

History of original corner establishment:

A surveyor makes reference to this corner in October of 1868.

Description of corner evidence found:

Set the corner by projecting a line through the West 1/4 and center 1/4 corners of Section 26, and intersecting this line with the East line of Section 26.

County Surveyor _____

Approved: HARLEY A. SIME
MONROE CO. SURVEYOR

**See Reverse Side
For Maintenance**



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set Harrison, flush, with a large field stone 1.5' to the southwest.

Witnesses to corner location:

Jung

Malliet



COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Adrian

County of Monroe