

105


**U.S. PUBLIC LAND CORNER
MAINTENANCE**

**Corner ID : SE Sec. 27, T18N-R1W
21801270000**

<u>FIELD DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE -----</u>
September 22, 2017	Zachariah P. Dechant Gary L. Dechant	Existing 2" iron pipe, set new sign 1' east

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 1" x 24" iron pipe, on forty line	N0°48'27"W	117.73'
2) Set 1" x 24" iron pipe on forty line	N0°48'27"W	267.62"
3) Set 3/4" x 4' round iron bar	S60E	25.11
4) Existing 3/4" Round iron bar DOT marker at interstate fence	S2°15'35"E	368.34'
5) Set 3/4"x4' round iron bar	S36W	30.24'
6) Set 1" x 24" iron pipe on forty line	S89°34'46"W	104.82'
7) Existing 3/4" round iron bar at interstate fence	S89°34'46"W	316.00'



CERTIFIED LAND CORNER

No. 105 (2)

CERTIFICATE

I, Bryan H. Meyer, do hereby certify that on the 1st day of November, 2005, I found (evidence) ~~(no evidence)~~ of the Northwest corner of Section 34 35, T 18 N, R 1 W Fourth principle Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 23rd day of February, 2006

Bryan H. Meyer
Registered Land Surveyor
Title

History of corner establishment since Original Government Survey


This corner was perpetuated by Harley A. Sime sometime in 1974 as illustrated by a tie sheet dated March 17, 1975. The original pipe monument was replaced by a longer pipe on September 4, 1981. I found the pipe intact and aquired new ties as shown below.



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner.


Witnesses to corner location:

Bryan Meyer
Gerald Hibbard



- ⊙ = Existing 2" iron pipe
- ⊠ = Existing GPS Azimuth mark
- ⊗ = Set Parker-Kalon (PK) nail

- 1= Set 2'±NE of NE edge concrete and 2'± SE of SE face of steel guard rail
- 2= Set 2'±SE of steel guard rail off of "<MADISON " sign
- 3= Set off of large white paint mark to the southeast.



O = Corner Location
T 18 N R 1 W
WISCONSIN

SURVEY CONTROL ORDER

Horizontal		MONROE COUNTY COORDINATE SYSTEM		
Corner	Northing	Easting	Elevation	
Control Station Name				

~~City, Village or~~ Town of LaGrange
County of Monroe

I, Harley Sime, do hereby certify that on the _____ day of _____ 1974, I found (evidence) ~~(no-evidence)~~ of the NW corner of Section 35, T 18 N, R 1 W., Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 17 day of March 1975.

Harley Sime
 COUNTY SURVEYOR
 Title

History of original corner establishment:

**See Reverse Side
 For Maintenance**

Description of corner evidence found:



Found an existing 3" iron pipe in good condition and left alone

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

A 3" pinched iron pipe up 12" in the swamp grass was found to be in good condition and let alone, with accessories as follows :

Witnesses to corner location:

- SURVEY CREW
K. Pritzlaff - Survey Crew Chief
D. Malliet
B. Jung
A. Lueck



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange

County of Monroe

PLACED
 COUNTY SURVEYOR'S
 SIGN 5-2987

COUNTY SURVEYOR FORM NO. 1