

108

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

Corner ID : S1/4 Sec.28, T18N-R1W

21801280020

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
July 20, 2015	Zachariah P. Dechant Gary L. Dechant	Existing 1- 1/4" round iron bar in centerline northbound lane USH "12"

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" hex iron bar 4' east of east curb of driveway exit for Timberwood Bank Office building. 11' north of sidewalk.	N77°14'58"E	141.46'
2) Existing 3/4"x24" round iron bar. Northwest corner Lot 1 Vol. 24 CSM P. 148. Down 8"	S69°34'31"E	162.13'
3) Set 3/4"x24" hex iron bar 1' east of street light at car wash	S50°51'09"W	210.54'
4) Set 3/4"x24" hex iron bar 17' NE of Timberwood Bank sign	N68°38'06"W	160.99'

ASSUMED BEARINGS.



CERTIFICATE

CERTIFIED LAND CORNER

No. 108

I, Harley A Sime, do hereby certify that on the _____ day of _____ 19 74, I found (evidence) (no-evidence) of the S 1/4 corner of Section 28, T 18 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 23 day of July 19 75.

Harley A Sime
County Surveyor
Title

History of original corner establishment:

Description of corner evidence found:



Found an existing 1-1/4" iron bar at this corner site and tied it in.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Found existing 1 1/4" iron bar flush with the pavement with accessories as follows :

Witnesses to corner location:

~~Kim H Pritzlaff~~ Survey Crew Chief
A. Lueck
D. Maliet
B. Jung



SIGN PLACED 12/16/86
Meyer, Kenworthy

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange
County of Monroe

COUNTY SURVEYOR FORM NO. 1