

87

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


**Corner ID : SE Sec. 21, T18N-R2W
21802210000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
November 11, 2016	Zachariah P. Dechant Gary L. Dechant	Existing Harrison, top broke off, down 8" at intersection of Fireworks Ave & Edgewater Road

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6", 11' SW of 12" Jack Pine	N46E	68.00'
2) Set 3/4"x24 round iron bar, down 6"	S44E	48.87'
3) Set 3/4"x24" round iron bar, down 10" in field, north side of large stone also down 10"	S46W	46.86'
4) Set 3/4"x24" round iron bar, down 6", 7' south of 26" White Pine	N44W	72.67'

Harrison & reference markers set on straight lines.

Gary L. Dechant

December 20, 2016

I, William C. Jung, do hereby certify that on the 22ND day of June 19 79, I found (evidence) ~~(no evidence)~~ of the Northwest corner of Section 27, T 18 N, R 2 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 10th day of Feb. 1981.

William C. Jung
 William C. Jung, R.L.S. 1323
 Title

History of original corner establishment:

Duane Marten set an iron bar at this corner in July of 1972.

Description of corner evidence found:

Found the monument of record at the occupied corner, removed the iron bar, and set a Harrison marker, down 6" in road centerlines.



**See Reverse Side
For Maintenance**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Jung

Pietz



NOTE: TREES DOUBLE BLAZED WITH NAIL & CAP SET

Approved: **HARLEY A. SIME**
MONROE CO. SURVEYOR

SURVEY CONTROL ORDER


Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

_____ or Town Greenfield

County of Monroe



COUNTY SURVEYOR FORM NO. 1