


CERTIFICATE

I, Nicholas M. Hillmer, do hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Wisconsin.

Dated this 21st day of May, 2013



Nicholas M. Hillmer, P.L.S. 2909
Anderson Engineering of Minnesota, LLC.

CERTIFIED LAND CORNER

History of corner established since Original Government Survey

Harley Sime set an iron pipe at this corner in November of 1965. In September of 1981, William Jung found Sime's iron pipe was disturbed by earth moving equipment. Jung set a Harrison monument on line and equidistant between the section corners.

Description of evidence found

On August 10th, 2012, Anderson Engineering of Minnesota located the Harrison monument flush with the ground and 1 foot southwest of a 4 inch square wood post with survey marker sign. A downed barbed wire fence is 1 foot west of the monument.

No. 21803040020



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:



Nick Hillmer
Josh Oslund
Dan Greenwald

MONROE COUNTY
COORDINATE SYSTEM
NAD 1983 (2007)

HARRISON MONUMENT
Northing (Y) 421347.63
Easting (X) 644260.66

Base Station - 22 182W
Northing (Y) 408053.25
Easting (X) 679287.00

All distances are shown in U.S. Survey Feet.
Ties are to 60D nails set in trees, except as noted.
Bearings are for tie reference purposes only.
Coordinates were derived from RTK GNSS procedures.



⊕ = LOCATION CORNER
Corner I.D. S 1/4 4
T 18 N R 3 W
Town of La Fayette
Monroe County, WI.

21803040020

I, William C. Jung, do hereby certify that on the second day of September 1981, I found (evidence) ~~of the~~ of the South 1/4 corner of Section 4, T 18 N, R 3 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of corner establishment since Original Government Survey

Harley Sime set an iron pipe at this corner in November of 1965.


Description of corner evidence found:

Found Sime's iron pipe disturbed by earth moving equipment. Reset the corner on line and equidistant between the section corners.

Dated this 3rd day of Sept. 1981

William C. Jung

William C. Jung, R.L.S. 1323
Title





COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

- William C. Jung
- Gary L. Dechant
- Carlton R. Pietz
- Bryan H. Meyer

Approved: **HARLEY A. SIME**
MONROE CO. SURVEYOR



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~Village of~~ Town of Lafayette
County of Monroe