

I, Harley A. Sime, do hereby certify that on the _____ day of October, 1975, I found (evidence) (~~no evidence~~) of the West 1/4 corner of Section 16, T 19 N, R 1 W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

Description of corner evidence found:

Dated this 2nd day of March 1976.

Duane Marten found a 1" iron pipe at this corner on December 24, 1971, removed the pipe, and replaced it with a Harrison marker. Sime and Malliet found the Harrison in October of 1975.

County Surveyor

UPDATE: This corner was obliterated during the course of new construction. The corner was re-established based on previous survey data. All the ties of record were destroyed. A new monument was set and ties established as illustrated below. Douglas J. Malliet, R.L.S.1266
8 September 1997

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:



Found a Harrison, down 2 to 3 inches.

Witnesses to corner location:

G. Sime-Crew Chief


D. Malliet

CREW: Douglas J. Malliet, R.L.S.
Bryan H. Meyer, R.L.S.
8 September 1997



- = existing 3/4" round iron bar
- = set 3/4" x 24" round iron bar
- = set nail/spike
- (R) = recorded bearing/distance
- ⊠ = set sign & post

Bearings are magnetic, unless noted otherwise.



○ = LOCATION CORNER

T 19 N R 1 W

WISCONSIN

SURVEY CONTROL ORDER

Horizontal _____

Vertical _____

| Corner | East (X) | North (Y) | Elevation (Z) | Zone |
|-------------------|----------|-----------|---------------|------|
| Control Sta. Name | | | | |

City, Village or Town Lincoln

County of Monroe