

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

112

Corner ID: S1/4 Sec. 30, T17N-R3W
21703300020

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT INFO</u>
April 16, 2020	Zachariah P. Dechant Gary L. Dechant	Existing 3/4"x18" round iron bar. Replaced 3/4" with a 1"x30" round iron bar, 18' south of impala Ave, 11' west of driveway 10669 Impala, 3.5' north of west end of culvert

	<u>Compass Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 10", 5' east of fence, 33' north of road	North	53.59'
2) Set 3/4"x24" round iron bar, down 6", 18' east of driveway	S55E	42.33'
3) Set 3/4"x24" round iron bar, down 6", 12' west of driveway	South	38.07'
4) Set 3/4"x24' round iron bar, down 10", 11 west of fence	N23W	55.47'
5) Existing 3/4" round iron bar between survey sign & address post	S29W	10.64'

Corner and reference markers 1 and 3 set on straight line.



I, Garold A. Sime, do hereby certify that on the 29th day of June 19 81 I found ~~(evidence)~~ (no evidence) of the S¹/₄ corner of Section 30, T. 17 N, R. 3 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 24th day of Sept. 19 81.

Garold A. Sime, R.L.S. 1261

County Surveyor's Office

Garold A. Sime

History of corner establishment since Original Government Survey

Fred Holden was at this corner in 1905.
I set a Harrison Monument at this corner in March of 1978. This monument has been destroyed by excavation in the area, also most of the ties were destroyed.

Description of corner evidence found:

I reset this corner using previous surveys done in Sec.30. This fit the ex. tie to the nail & cap in the power pole north of the Road.



See Reverse Side For Maintenance

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Sime

C. Pietz



Approved: **HARLEY A. SIME**
MONROE CO. SURVEYOR

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM				
Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town Angelo
County of Monroe

COUNTY SURVEYOR FORM NO. 1

I, Garold A. Sime, do hereby certify that on the 24 day of March 19 78, I found (evidence) (no evidence) of the N~~A~~ corner of Section 31, T 17 N, R 3W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 24 day of March 19 78.

Garold A. Sime

Garold A. Sime, Co. Surveyors Office
Title

History of original corner establishment:

Fred Holden was at this corner in 1905

**See Reverse Side
For Maintenance**

Description of corner evidence found:

Set this corner by single proportionate measurement using the measured distance between the SW corner and the S1/16SW corner and proportioning to the Original Government Notes.




Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G.A. Sime Crew Chief

C. Pietz

G. Dechant



O = LOCATION CORNER
T 17 N R 3W
WISCONSIN

Approved by H.A. Sime, Monroe County Surveyor

SURVEY CONTROL ORDER

Horizontal _____
Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Angelo

County of Monroe

COUNTY SURVEYOR FORM NO. 1