

I, Harley A. Sime, do hereby certify that on the 10th day of September 1979, I found (evidence) ~~(no evidence)~~ of the Northeast corner of Section 16, T16 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 17th day of Feb. 1981.

Approved: HARLEY A. SIME
MONROE CO. SURVEYOR
Title

History of original corner establishment:

Gary Sime set a 3/4" iron bar at the occupied corner in July of 1976. James Carroll used this bar as the corner in his survey of November, 1976. Gary Sime again used this corner in a February, 1977 survey.

Description of corner evidence found:

Found the corner of record, removed the iron bar and replaced it with a Harrison marker. Accepted the corner as the best available evidence of the original government survey.

UPDATE: Found the existing Harrison monument at this corner location lying loosely in a water-filled hole. The only bearing tree for this corner was gone. Gary Dechant had visited this corner just prior to our 9-19-96 visit, and had re-established this corner location. Four new corner ties were established.



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner: Douglas J. Malliet, R.L.S. #1266, 19 September 1996

Witnesses to corner location:

Pietz

Tormoen

COUNTY SURVEYOR FORM NO. 21



CREW: Douglas J. Malliet, R.L.S.
 Tim Wilson
 9-19-96

SURVEY CONTROL ORDER

Horizontal _____

Vertical _____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

_____ or Town Clifton

County of Monroe

4434

CERTIFICATE

CERTIFIED LAND CORNER

No. 47

41601090000

I, Harley A. Sime, do hereby certify that on the 10th day of September 1979, I found (evidence) (~~no evidence~~) of the Northeast corner of Section 16, T16 N, R 1 E, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

Gary Sime set a 3/4" iron bar at the occupied corner in July of 1976. James Carroll used this bar as the corner in his survey of November, 1976. Gary Sime again used this corner in a February, 1977 survey.

Description of corner evidence found:

Found the corner of record, removed the iron bar and replaced it with a Harrison marker. Accepted the corner as the best available evidence of the original government survey.

Dated this 17th day of Feb. 1981.



Approved: HARLEY A. SIME
MONROE CO. SURVEYOR
Title

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Pietz
Tormoen



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

_____ or Town Clifton
County of Monroe