

# 95

**U.S. PUBLIC LAND CORNER  
MAINTENANCE**

**Corner ID : E1/4 Sec.30, T16N-R1E**

**41601302000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE -----</u>
August 28, 2014	Zachariah P.Dechant Gary L. Dechant	Found crow bar in rock pile on SW corner of steel fence post, 5' east of new square corner post. Bearing trees dead.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" square iron bar, down 12" in pasture	N34E	28.75'
2) Set 3/4"x24" square iron bar, down 12" in field	S42E	24.38'
3) Set 3/4"x24" square iron bar, down 6", 4' south & 13' west of new fence corner	S85W	17.74'
4) Set 3/4"x24" square iron bar, down 12" in field	N48W	23.69'

**COORDINATES:**



I, Gary L. Dechant, do hereby certify that on the 14th day of December 1984, I found (evidence) ~~(no evidence)~~ of the E<sup>1</sup>/<sub>4</sub> corner of Section 30, T 16 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 19th day of Dec. 1984.

Gary L. Dechant  
 Registered Land Surveyor, 1744  
Title

History of corner establishment since Original Government Survey

No known history since the original government survey.

**See Reverse Side For Maintenance**

Description of corner evidence found:

Accepted fence corner as the best available evidence as it fits conditions well.



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Dan Rattle

Gary Dechant

No other ties in area, all open field.



● = LOCATION CORNER

(Trees double blazed with N&C's)



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Clifton

County of Monroe

COUNTY SURVEYOR FORM NO. 1