

# 76

**U.S. PUBLIC LAND CORNER  
MAINTENANCE**

**Corner ID : E1/4 Sec.20, T17N-R1E**


**417012020000**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE -----</u>
October 3, 2014	Zachariah P.Dechant Gary L. Dechant	Harrison destroyed by utility company. Barn corner only tie remaining. Reset from previous surveys. Reset cast iron TCP in concrete with 4" anchor, hit bedrock. 15' south of Honeysuckle Avenue. Fire no 30092 sign post with survey sign 1' north. When digging exposed telephone wires. Wires are on south side of TCP and about 2" deeper.

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" square iron bar, down 6", north of driveway	N37E	27.65'
2) Set 3/4"x24" square iron bar, down 6" south side of driveway leading to hay mow of barn	S68E	40.80'
3) Set 3/4"x24" square iron bar, down 6", 6' west of 6" White Oak 12' west of trail	S78W	37.86
4) Set 3/4"x24" square iron bar, down 6", 15' south of Honeysuckle Ave.	N44W	41.05'
5) NW corner of barn	S71E	92.65'

*Gary L. Dechant*



*October 3, 2014*

I, Harley A. Sime 21st, do hereby certify that on the 21st day of December 1979, I found (evidence) ~~(no evidence)~~ of the West 1/4 corner of Section 21, T 17 N, R 1 E Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 21st day of Dec. 1979.

**Approved: HARLEY A. SIME**  
**MONROE CO. SURVEYOR**  
 Title

History of corner establishment since Original Government Survey

No known history since the original government survey.

Description of corner evidence found:

Harley A. Sime set an iron pipe here in an earlier survey. Found the iron pipe laying flat on top of the ground. Reset corner off survey points from a previous survey done by G. Sime who also used this corner. Set a Harrison Monument.


**See Reverse Side For Maintenance**

COUNTY SURVEYOR FORM NO. 1



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

- G. Dechant
- B. Meyer
- T. Tormoen



NOTE: All trees double blazed w/ N&Cs set.



O = LOCATION CORNER  
 T 17 N R 1 E  
 WISCONSIN

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Oakdale  
 County of Monroe  
Wisconsin