

CERTIFICATE

CERTIFIED LAND CORNER

No. 24

21502020020

I, Gary L. Dechant, do hereby certify that on the 19th day of April 2002, I found (evidence) (~~no evidence~~) of the S/4 corner of Section 2, T 15 N, R 2 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 25th day of April 2002.

Gary L. Dechant

Registered Land Surveyor

Title

History of corner establishment since Original Government Survey

No known recorded history since the original government survey.

Description of corner evidence found:



Found remains of Original Gov't. B.T., N10E, 11.88 lks. Tree is now fallen and rotted measuring 24"± in diameter. Measurement to the brook to the west also supports this location. Down fence corner is 10' north and 14' east. There is a shortage to the east that could be due to terrain and a drop of chain in the Original Government Survey. Most fences in the section do not measure well probably for the same reasons.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Zachariah P. Dechant

Gary L. Dechant



WISCONSIN

Trees double blazed with 40d nails set.

COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town SHELDON
County of MONROE