

21601010000

I, Gary L. Dechant, do hereby certify that on the 30th day of September 19 87, I found ~~(evidence)~~ (no evidence) of the SE corner of Section 1, T 16 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 6th day of Oct. 19 87.

Gary L. Dechant

Registered Land Surveyor, 1744
Title

History of corner establishment since Original Government Survey

No known recorded history since the original government survey. U.S.G.S. map shows a corner here, but was almost certain to have been dug out because of the gravel pit now surrounding it (gravel pit abandoned).

Description of corner evidence found:

Set at the intersection of lines formed between the SW and S 1/4 corners of Section 1 and between the E 1/4 Section 1 and the E 1/4 corner of Section 12. This location fits segment of fence found approx. 600'+ west of this corner very well. The half mile distances along the south line of Section 1 are also very close to being equal using this computed location for the SE of Section 1, and the same for the East line of Section 1.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

David E. Madison

Gary L. Dechant

ROCK OUTCROP
2nd LEDGE
DOWN

NAIL & CAP

26.90'
S 89° W



31.26'
S 38° E

50.19'
N 76° E

CHISELLED ON
STONE FACE

Set 2 1/2"x7' iron bar on south slope, 23.5 feet south of top of hill. Layered flat shale stone around iron bar. Sign placed 23.5' North (Top Hill)

NAIL & CAP IN
OUTCROP
18' DIA.



COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City/Village/Town Wilton
County of Monroe