

CERTIFICATE

CERTIFIED LAND CORNER

No. 103

21604260000

I, Gary L. Dechant, do hereby certify that on the 30th day of July 19 91, I found (evidence) (no evidence) of the SW corner of Section 25, T 16 N, R 4 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of corner establishment since Original Government Survey

Henry Schroeder set an iron pipe here in 1915.

Description of corner evidence found:

I could not find Schroeder's iron pipe, it may have been destroyed when the power line came through or when the ditch was dug. Reestablished this corner on line and at a doubled distance between the NW and W corners of Section 25. This location fits the remains of and east-west fence line extremely well.

Dated this 30 day of July 19 91.

Gary L. Dechant




Reg. Land Surveyor, S-1744

COUNTY SURVEYOR FORM NO. 1

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Gary L. Dechant



Set 2"x5' iron pipe in wet marsh. Set Stones obtained from creek bottom around the iron pipe. Corner falls 3' South and 6' East of creek intersection. Set survey sign at power pole shown as tie. Railroad spike 11.31 feet to west is on dry, higher ground.

SURVEY CONTROL ORDER table with columns for Horizontal and Vertical.

WISCONSIN COORDINATE SYSTEM table with columns for Corner, Control Sta. Name, East (X), North (Y), Elevation (Z), and Zone.

City, Village, Town LEON, County of MONROE