

84

**U.S. PUBLIC LAND CORNER
MAINTENANCE**

Corner ID : S1/4 Sec. 23, T17N-R1W
21701230020

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE -----</u>
October 21, 2016	Zachariah P.Dechant Gary L. Dechant	Existing Harrison intact, set stones around Harrison, Set new sign 1.5' west. On steep NW slope near top of hill

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6", east of fence, 4' SW of 14" Red Oak	N38E	19.74'
2) Set 3/4"x24" round iron bar, down 6"	S26E	7.87'
3) Set 3/4"x24" round iron bar, down 6", 4' NE of 8" Red Oak	S30W	17.00'
4) Set 3/4"x24" round iron bar, down 6"	N30W	8.37'

Gary L. Dechant
GARY L. DECHANT
5-1744
CAMP
DOUGLAS, WI
LAND SURVEYOR
November 29, 2016

I, Harley A. Sime, do hereby certify that on the 1st day of July 19 81, I found ~~(evidence)~~ (no evidence) of the S¹/₄ corner of Section 23, T 17 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 25th day of August 19 81.

Harley A. Sime, R.L.S. 355

County Surveyor

Approved: **HARLEY A. SIME**

MONROE CO. SURVEYOR

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

B. Meyer

G. Dechant

History of corner establishment since Original Government Survey

No known recorded history since the original government survey.



Description of corner evidence found:

Set on line and equidistant between the SW and SE corners of Section 23.

See Reverse Side For Maintenance

COUNTY SURVEYOR FORM NO. 1

(All trees double blazed with nail set in lower blaze)



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town Tomah
County of Monroe