

# 82

**U.S. PUBLIC LAND CORNER  
MAINTENANCE**


**Corner ID : S1/4 Sec24, T17N-R1W  
21701240020**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE -----</u>
July 9, 2014	Zachariah P. Dechant Gary L. Dechant	Found Harrison in tact, survey sign 1' west, steel post 1' east, east west fence no longer in place

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" hex iron bar, in field, down 16"	N16E	24.70'
2) Set 3/4"x 24" hex iron bar, in field, down 12"	S73E	45.15'
3) Set 3/4"x24" hex iron bar, in field, down 12"	S25E	41.26'
4) Set 3/4"x24" hex iron bar, in field, down 12"	S58W	36.54'

**COORDINATES:**



I, Bryan H. Meyer, do hereby certify that on the 9<sup>th</sup> day of July 19 86, I found ~~evidence~~ (no evidence) of the North 1/4 corner of Section 25, T 17 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 15<sup>th</sup> day of Dec. 1986.

Bryan H. Meyer  
Deputy County Surveyor  
Title

History of corner establishment since Original Government Survey

Nothing recorded.

See Reverse Side  
For Maintenance

Description of corner evidence found:

I set this corner equi-distant between the Northwest and Northeast corners of Section 25 in the East-West fenceline.



COUNTY SURVEYOR FORM NO. 1




Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Crew: Wilhite, Tralmer  
Date: July 9, 1986  
Weather: Sunny, 75°±.  
Witnesses to corner location:

Dallas Wilhite

Joel Tralmer

NOTE: The bearings shown hereon are magnetic hand compass bearings.



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town of Tomah  
County of Monroe