

# 15 B

**U.S. PUBLIC LAND CORNER  
MAINTENANCE**

**Corner ID : C1/4, Sec.5, T17N-R3W**

**21703052020**

<u>DATE</u>	<u>CREW</u>	<u>MONUMENT TYPE</u> -----
March 29, 2017	Zachariah P.Dechant Gary L. Dechant	Existing 1¼" square iron bar, south of long driveway easement, east of CTH "I" Set new sign 1' north

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" round iron bar, down 6", between post of DNR/LaCrosse River sign	S54E	65.48'
2) Set 3/4"x24" round iron bar, down 6", 5' east of 20" Burr Oak (BT)	S5E	35.24'
3) Set 3/4"x24" round iron bar, down 6", 6' NE of 16" Ash	S29W	25.41'
4) Set 3/4"x24" round iron bar, down 6", 1' west of fence corner north of driveway easement	N1W	49.25'



I, Harley A. Sime, do hereby certify that on the 17<sup>th</sup> day of July 19 75, I found (evidence) ~~(no evidence)~~ of the C<sup>1</sup>/<sub>4</sub> corner of Section 5, T17 N, R3W, Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 1 day of June 1977.

History of original corner establishment:

Description of corner evidence found:

Found existing 3/4" Iron bar and replaced it with a 1" square iron bar. This was an occupied center.

**See Reverse Side For Maintenance**



~~County Surveyor~~ **Approved: HARLEY A. SIME**  
~~title~~ **MONROE CO. SURVEYOR**

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

K. Pritzlaff - Crew Chief

C. Pietz



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Angelo

County of Monroe

COUNTY SURVEYOR FORM NO. 1