

32

**U.S. PUBLIC LAND CORNER
MAINTENANCE**


**Corner ID : S1/4 Sec. 6, T17N-R3W
21703060020**

DATE	CREW	MONUMENT TYPE -----
October 7, 2016	Zachariah P. Dechant Gary L. Dechant	Existing Harrison, top broke off, over stone. Down 12". 27' north & 8' west of CTH "Q"/Gardener Ave intersection Set mag nail 1' north and small bolt 1' east

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4" x24" round iron bar, down 6", 4' SW of 6" Burr Oak	N54E	59.69'
2) Existing 3/4" iron pipe, down 6"	East	33.00' (33.00)'
3) Set 3/4"x24" round iron bar, down 6"	S54W	102.91"
4) Set 3/4"x24" round iron bar, flush, 4' north of 13" Ash	N69W	34.18

Harrison and reference markers 1 & 3 set on straight line.



I, Gary L. Dechant, do hereby certify that on the 27th day of October 1987, I found (evidence) ~~(in existence)~~ of the N¹/₄ corner of Section 7, T 17 N, R 3 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 9th day of Nov. 1987.

Gary L. Dechant
Registered Land Surveyor, 1744
Title

History of corner establishment since Original Government Survey

**See Reverse Side
For Maintenance**

Description of corner evidence found:



George Baker, Monroe County Highway Commissioner, contacted the County Surveyor's Office and requested removal of the iron pipe marker at this corner as highway repair was needed. New ties were taken, checked existing ties, reset corner after highway repair was completed.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

David E. Madison

Timothy S. Frederick



SURVEY CONTROL ORDER

Horizontal _____
Vertical _____

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

WISCONSIN COORDINATE SYSTEM

City, Village or Town Angelo
County of Monroe

COUNTY SURVEYOR FORM NO. 1

I, Harley A. Sime, do hereby certify that on the 11th day of July 19 75, I found (evidence) ~~(no evidence)~~ of the North 1/4 corner of Section 7, T 17 N, R 3 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 8th day of April 19 77.

History of original corner establishment:

Fred A. Holden found stone in May, 1910.

Description of corner evidence found:

Found a 2 1/2" iron pipe set over a stone.

See Reverse Side For Maintenance

County Surveyor

Approved: **HARLEY A. SIME**
MONROE CO. SURVEYOR

3/12/81

Bergman set an iron by the stone in April of 1942. *axg*

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:



North 1/4 corner Section 7, iron over stone.

Stone is buried 20"

Witnesses to corner location:

Jung

Dechant



SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town Angelo

County of Monroe

COUNTY SURVEYOR FORM NO. 1