

CERTIFICATE

I, Nicholas M. Hillmer, do hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Wisconsin.

Dated this 23rd day of May, 2013



Nicholas M. Hillmer, P.L.S. 2909
Anderson Engineering of Minnesota, LLC.

CERTIFIED LAND CORNER

History of corner established since Original Government Survey
Fred Holden was at this corner in 1905. Harley Sime found a 3/4 inch iron bar and accepted it as the corner. Sime replaced the iron with a Harrison monument.

Description of evidence found

On February 27th, 2013, Anderson Engineering of Minnesota located the Harrison monument 0.1 feet above grade and 1 foot north of a witness post with a survey marker sign.

No. 21703190000



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Nick Hillmer
Josh Oslund
Dan Greenwald



MONROE COUNTY
COORDINATE SYSTEM
NAD 1983 (2007)

HARRISON MONUMENT
Northing (Y) 373854.29
Easting (X) 637144.41

Base Station - 22 182W
Northing (Y) 408053.25
Easting (X) 679287.00



All distances are shown in U.S. Survey Feet.
Bearings are for tie reference purposes only.
Coordinates were derived from RTK GNSS procedures.



⊗ = LOCATION CORNER
Corner I.D. SE 19
T 17 N R 3 W
Town of Angelo
Monroe County, WI.

CERTIFICATE

UPDATED
CERTIFIED LAND CORNER

21703190000

No. 91

Page 2

I, Harley A. Sime, do hereby certify that on the 4th day of June 19 76, I found (evidence) ~~(no evidence)~~ of the Southwest corner of Section 20, T. 17 N, R. 3 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 7th day of April 19 77.

County Surveyor
Title

History of original corner establishment:

Fred A. Holden was at this corner in 1905.

Description of corner evidence found:

Removed a 3/4" iron bar and replaced it with a Harrison marker. The fence corner had been used as best available evidence.

UPDATE: While performing survey work in this area, we found that this corner was in need of additional ties. New ties were taken and a sign set.

B.A.M. BHM 1/14/99


Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set Harrison, up 1"


Witnesses to corner location:

Jung

Dechant




Set sign and post near corner



4" Oak - double blazed distance is to a nail set in a hack in the side of the tree

UPDATE CREW: Meyer, Miller
November 17, 1998

- = Existing 3/4" round iron bar
- ⊙ = Set 3/4" x 24" round iron bar
- ⊕ = Existing cast iron Harrison marker
- ⊗ = nail in the face of a power pole



COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village, or Town~~ Angelo

County of Monroe