


CERTIFICATE

I, Nicholas M. Hillmer, do hereby certify that this document and the data contained herein was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Wisconsin.

Dated this 23rd day of May, 2013



Nicholas M. Hillmer, P.L.S. 2909
Anderson Engineering of Minnesota, LLC.

CERTIFIED LAND CORNER


History of corner established since Original Government Survey

The 1940's McCoy boundary notes show a corner at this location. In April of 1981 Harley Sime found the McCoy marker and did not accept the corner after surveying the section. Sime set a Harrison monument by using single proportionate measurement.

Description of evidence found

On August 31st, 2012, Anderson Engineering of Minnesota located the Harrison monument flush with the ground and 0.2 feet south of a metal post with survey marker sign. The McCoy monument shown on Sime's 1981 certified land corner certificate was not found.

No. 21703222000



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:



Witnesses to corner location:

Nick Hillmer
Josh Oslund
Dan Greenwald

MONROE COUNTY
COORDINATE SYSTEM
NAD 1983 (2007)

HARRISON MONUMENT
Northing (Y) 376405.76
Easting (X) 653000.20

Base Station - 22 182W
Northing (Y) 408053.25
Easting (X) 679287.00



⊙ = LOCATION CORNER
Corner I.D. E 1/4 22
T 17 N R 3 W
Town of Angelo
Monroe County, WI.

All distances are shown in U.S. Survey Feet.
Ties are to 60D nails set in trees.
Bearings are for tie reference purposes only.
Coordinates were derived from RTK GNSS procedures.

2170322000

I, Harley A. Sime, do hereby certify that on the 28th day of April 1981, I found ~~(evidence)~~ (no evidence) of the W/4 corner of Section 23, T17 N, R 3 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 15th day of June 1981.

Harley A. Sime, R.L.S. 355

County Surveyor

Title

History of corner establishment since Original Government Survey

WWII McCoy shows a monument here during the Camp McCoy boundary survey of 1945.
survey

Description of corner evidence found:

Found McCoy marker, but after surveying the section, found the monument to be in error; therefore could not accept it as the corner. The corner was set by single proportionate measurement.



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

G. Dechant

C. Pietz

COUNTY SURVEYOR FORM NO. 1



● = LOCATION CORNER

T 17 N R 3 W

WISCONSIN

Approved: **HARLEY A. SIME**
MONROE CO. SURVEYOR

(All trees double blazed with R.R. spikes set)

SURVEY CONTROL ORDER

Horizontal	_____
Vertical	_____

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

~~City, Village or~~ Town Angelo

County of Monroe