

CERTIFICATE

CERTIFIED LAND CORNER

No. 19

**21801022000**

I, Harley A. Sime, do hereby certify that on the 15th day of October 1975, I found ~~(evidence)~~ (no evidence) of the East 1/4 corner of Section 2, T 18 N, R 1 W Fourth Principal Meridian, and I re-established said corner according to the Wisconsin Statutes as shown and described hereon.

History of original corner establishment:

Description of corner evidence found:

Dated this 5th day of Feb., 1976

Harley A. Sime  
County Surveyor  
Title

Set the corner proportionately between the section corners.




Note: Arnold Storkel testified that when the drainage ditch was put in to the North, it was supposed to have been put in on the section line. He also said that there used to be a road in on the 1/4 line to the East, and that when the road was closed, they merely built a fence in the middle of the old road. The old Monroe County plat book of 1915 shows this road.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Set a 2 1/2"x7' pipe, up 3', in the middle of the creek (ditch).

Witnesses to corner location:

W.C. Jung-Crew Chief W.C. Jung  
A. Lueck



COUNTY SURVEYOR FORM NO. 1

SURVEY CONTROL ORDER

Horizontal \_\_\_\_\_  
Vertical \_\_\_\_\_

WISCONSIN COORDINATE SYSTEM

Corner	East (X)	North (Y)	Elevation (Z)	Zone
Control Sta. Name				

City, Village or Town La Grange  
County of Monroe